



EuroPHit_OP21_MosArt_Family Home_Ireland

ROEA01 Eaves detail for masonry wall - Site Photo

BEFORE AF



AFTER



DESCRIPTION/CHALLENGES

16.03.2016

Mariana Moreira

Scale Author

Date

In order to assure a continuous airtight line, it has been decided to keep the airtight layer along the outside of the existing block wall as the existing render, and lay on the existing roof rafters an airtight membrane that will join the wall render at eaves and verge junctions.



The sole responsibility for the content of this publication lies with the authors. It does not necessarily reflect the opinion of the European Union. Neither the EACI nor the European Commission are responsible for any use that may be made of the information contained therein.



